


MO 19

T Centrale

Tee fitting

Raccord à Té central

T -Einschraubverschraubung



Tipo	Øe Tubo	D1	L1	L2	L3	CH1	CH2	g Δ
19 04 18	4	R1/8	8	16	21	9	10	23
19 05 18	5	R1/8	8	17	23	9	12	31
19 06 18	6	R1/8	8	16	23	9	12	26
19 06 14	6	R1/4	11	20	24	11	12	30
19 08 18	8	R1/8	8	17	24	11	14	38
19 08 14	8	R1/4	11	20	24	11	14	41
19 10 14	10	R1/4	11	23,5	32	13	19	81
19 10 38	10	R3/8	11,5	24	32	13	19	92
19 12 38	12	R3/8	11,5	25,5	34,5	15	22	118
19 12 12	12	R1/2	14	28,5	34,5	15	22	125
19 15 12	15	R1/2	14	30	38	17	27	164


MO 20

T Laterale

Lateral Tee

Raccord Té Latéral

T -Verschraubung



Tipo	Øe Tubo	D1	L1	L2	L3	CH1	CH2	g Δ
20 04 18	4	R1/8	8	16	21	9	10	23
20 05 18	5	R1/8	8	17	23	9	12	30
20 06 18	6	R1/8	8	16	23	9	12	27
20 06 14	6	R1/4	11	20	24,5	11	12	29
20 08 18	8	R1/8	8	17	24	11	14	38
20 08 14	8	R1/4	11	20	24	11	14	41
20 10 14	10	R1/4	11	23,5	32	13	19	87
20 10 38	10	R3/8	11,5	24	32	13	19	92
20 12 38	12	R3/8	11,5	25,5	34,5	15	22	121
20 12 12	12	R1/2	14	28,5	34,5	15	22	130
20 15 12	15	R1/2	14	30	38	17	27	181


MO 21

Dado

Nut

Ecrou

Überwurfmutter



Tipo	Øe Tubo	D1	L	CH	g Δ
21 04 08	4	M8x1	11	10	4
21 05 10	5	M10x1	11,5	12	6
21 06 10	6	M10x1	11,5	12	6
21 08 12	8	M12x1	12	14	7
21 10 16	10	M16x1,5	15,5	19	19
21 12 18	12	M18x1,5	15,5	22	26
21 15 22	15	M22x1,5	17	27	43


MO 22

Ogiva

Olive

Bague

Schneidring



Tipo	Øe Tubo	L	g Δ
22 04 65	4	6	0,5
22 05 75	5	7,5	1
22 06 75	6	7	2
22 08 75	8	7	2
22 10 95	10	10	3
22 12 95	12	10	4
22 15 10	15	10	4,5